

Werkzeugliste Rechteck mit spitzen Ecken

Stand: 2016-12-21

Seite: 1

Breite:	Höhe:	Radius:
3,9	2	0
5,5	3,3	0
6	6	0
6	6	0
7	2	0
7,5	3	0
8	8	0
8,5	7,5	0
9	11	0
10	10	0
12,6	6,6	0
14	14	0
15,3	15	0
16,6	13,5	0
17	6	0
17	17	0
17,8	15,7	0
18	13	0
18	13	0
18	18	0
20,2	20,2	0
22	22	0
23,5	10	0
24	24	0
25	10	0
26	9	0
26	13	0
26	18	0
26	26	0
27	18	0
27	27	0
28	12	0
28	12	0
28	28	0
30	15	0
30	22	0
30	66	0
30	66	0
30,5	27	0
30,8	3,8	0
30,85	22,22	0
31,1	10,8	0

Breite:	Höhe:	Radius:
32	25	0
33	10	0
34,2	12,6	0
35	17	0
35	30	0
36	18	0
37	13	0
37	18	0
37	26	0
38	38	0
42	22	0
45	15	0
45	30	0
45	42	0
46	22	0
47	6	0
50	7	0
50	15	0
50	20	0
52	13	0
52	18	0
52	26	0
55	10	0
55	15	0
57	10	0
60	19	0
60	36	0
60	40	0
61	14	0
62	12	0
62	50	0
63	21,8	0
64,3	29,8	0
65	15	0
65	18,15	0
65	22	0
65,5	18,9	0
65,5	31,95	0
66	18,9	0
66	31,95	0
72	12	0
74	18,9	0

Werkzeugliste Rechteck mit spitzen Ecken

Stand: 2016-12-21

Seite: 2

Breite:	Höhe:	Radius:
74	31,95	0
74	33,9	0
74	37	0
74,3	20	0
87	42	0
87	45	0
95	12	0

Breite:	Höhe:	Radius: